


Z
281.92
272.54
267.32
278.41


C:\Documents and Settings\Roger_Kruger\My Documents\Current Jobs\1 - Week 27 July 4 4280 Radisson BluA, Linked site plan.mxd(2011.07.26, Radisson Blu- Kruger Park, 2007) linked site plan.rvt

- 1- FAMILY UNITS
- 2- HOTEL ROOMS
- 3- MAIN LODGE
- 4- BOMA
- 5- CONFERENCE CENTRE
- 6- FAMILY CENTRE
- 7- WELLNESS CENTRE
- 8- WASTE TREATMENT
- 9- RESERVOIR
- 10- RECYCLING DEPOT
- 11- LAUNDRY
- 12- STORES
- 13- STAFF FACILITY
- 14- SUBSTATION
- 15- ENTRANCE GATE
- 16- RIVERSIDE MEANDER
- 17- OFFICES
- 18- CATERING DECK
- 19- SUNDOWNERS DECK
- 20-
- 21- SODIAC SITE


1 Site Plan
1 : 1000



2 Road Section A
1 : 50



3 Road Section B
1 : 50



4 Road Section C
1 : 50

THIS DRAWING IS SUBJECT TO COPYRIGHT AND MAY NOT BE REPRODUCED IN WHOLE OR PART OR IN ANY MANNER WHATSOEVER WITHOUT WRITTEN PERMISSION FROM CRONJE ASSOCIATED ARCHITECTS CC


14	09/06/2011	1- Room plans indicated on site plan. 2- Main lodge complex shifted back to accommodate trees. 3- Fenceline straightened behind units. 4- Wellness Centre revised. 5- Wellness added between wellness centre and main lodge complex.		RK
13	08/04/2011	1- Family Centre moved upstairs. 2- Hotel Units rearranged to suit site. 3- Sundowner deck indented around tree. 4- Wapstone added. 5- Wellness centre repositioned around sensitive zone.		RK
12	14/03/2011	1- Units re-angled. 2- Last three units extended parallel to river. 3- Road widths revised.		RK
11	11/03/2011	1- 2-lane roads reduced to 1-lane roads with lay-bys.		RK
10	11/03/2011	1- Road width increased between the circle and North end to gravel road.		RK
9	10/03/2011	1- Sodac 30m buffer zones added. 2- Road layout changed. 3- Hotel unit layout changed to suit Sodac zones. 4- Service facility created and moved up the slope. 5- Entrance gate moved and road redirected.		RK
8	16/02/2011	1- Hotel Floor Layout changed. 2- Mad rooms amended.		RK
7	14/02/2011	1- Hotel room layout changed to skirt the Sodac site. 2- Raised Deck added in front of dining area at main lodge. 3- Manager's house moved to eastern side of staff facility car park. 4- Business zone added at reception.		RK
6	11/02/2011	1- Road section A made 1200mm wide. 2- Road Section C made 2500mm wide. 3- On road continued northwards. 3- Turning circle by main lodge complex made smaller.		RK
5	11/02/2011	1- Last 12 blocks of rooms and suites straightened in a westerly direction away from the river. 2- Entrance road to the service facility repositioned so that it is equidistant to the main entrance and main complex. 3- Circular second dock on main walkway along the Crocodile river removed.		RK
4	07/02/2011	1- Six master rooms added between hotel units.		RK
3	04/02/2011	1- Riverside Meander removed for later phasing.		RK
2	03/02/2011	1- Service Station moved down the slope away from the entrance gate.		RK
1	03/02/2011	1- Small Family unit changed to a 3 room module. 2- Pathways to units made narrower (1200mm wide). 3- Turning circle added.		RK
Rev	Date	Description	Issued by	Issued by
Revision Schedule				

- ISSUE FOR COUNCIL SUBMISSION
- FOR INFORMATION ONLY
- FOR TENDER PURPOSES ONLY
- CONTRACT DOCUMENTS
- ISSUE FOR APPROVAL
- ISSUE FOR CONSTRUCTION

PROJECT
Radisson Blu- Safari Hotel- Kruger National Park

DESCRIPTION
Site Plan

CRONJE ASSOCIATED ARCHITECTS CC
Suite E- MGA House
Wimble Close
Balford Business Park
Po Box 6438 Zimbali 4418
Tel: +27 32 946 3830/1
Fax: +27 32 946 3835
email: lewellyn@caarchitects.co.za
reg no 2821



Drawn
Roger
Project nr: Project Number
Sheet nr: 285-SK01-A100
Date
2011/07/05
01:06:28 PM
Rev Nr. 14